

# City of Henderson Fire Safety Engineering Informational Bulletin

Issue 013

COHFireSafety@CityofHenderson.com

June 27, 2006





## TOP TEN

# COMMON ERRORS ON SPRINKLER DRAWINGS (PART 1 OF 2)


1. Civil plans are not complete – or are missing information.

2. Hose allowance that is added in at the wrong place in the calculations.



3. Incomplete Building Section or missing information.

4. Sprinklers located along sloped roofs or ceilings that are not measured along the slope.



5. Elevations of sprinkler pipe on the drawings which do not match elevations shown on the calculations



Please e-mail comments, questions & suggestions regarding this bulletin to:  
[COHFireSafety@CityofHenderson.com](mailto:COHFireSafety@CityofHenderson.com) or call 702-267-3630

If you do not wish to receive this bulletin, send a reply with REMOVE in the subject line